

LISTA DE PRECIOS N°22 RETENES DBH (Guía de válvulas)



Nº DBH	Aplicación	Cod. Barra	P. FINAL
RT-567/1Pol	Alfa Romeo 145-146-155-T.D.-Mot.1.9/2.0D	DBH567AP	\$ 1.038
RT-567/1Vit	Alfa Romeo 145-146-155-T.D.-Mot.1.9/2.0D	DBH567AV	\$ 1.635
RT-567Pol	Alfa Romeo 145-146-155-T.D.-Mot.1.9/2.0D	DBH567P	\$ 8.415
RT-567Vit	Alfa Romeo 145-146-155-T.D.-Mot.1.9/2.0D	DBH567V	\$ 13.087
RT-558/1Pol	Alfa Romeo 164	DBH558AP	\$ 1.038
RT-558/1Vit	Alfa Romeo 164	DBH558AV	\$ 1.635
RT-558Pol	Alfa Romeo 164	DBH558P	\$ 8.415
RT-558Vit	Alfa Romeo 164	DBH558V	\$ 13.087
RT-554/1Pol	Arandela Deutz 913	DBH554AP	\$ 666
RT-568/1Pol	Audi 2.4 D-TD-TDi-A6-Motor 2.6/2.8-6 Cil	DBH568AP	\$ 1.038
RT-568/1Vit	Audi 2.4 D-TD-TDi-A6-Motor 2.6/2.8-6 Cil	DBH568AV	\$ 1.635
RT-568Pol	Audi 2.4 D-TD-TDi-A6-Motor 2.6/2.8-6 Cil	DBH568P	\$ 12.578
RT-568Vit	Audi 2.4 D-TD-TDi-A6-Motor 2.6/2.8-6 Cil	DBH568V	\$ 19.625
RT-570/1Pol	Audi 80-100-A4-A6 QUATRO-MOTOR 2.6/2.8	DBH570AP	\$ 1.163
RT-570/1Vit	Audi 80-100-A4-A6 QUATRO-MOTOR 2.6/2.8	DBH570AV	\$ 1.831
RT-570Pol	Audi 80-100-A4-A6 QUATRO-MOTOR 2.6/2.8	DBH570P	\$ 14.066
RT-570Vit	Audi 80-100-A4-A6-QUATRO-MOTOR 2.6/2.8	DBH570V	\$ 22.011
RT-569/1Pol	Audi A6-TDi-Turbo Diesel	DBH569AP	\$ 1.038
RT-569/1Vit	Audi A6-TDi-Turbo Diesel	DBH569AV	\$ 1.635
RT-569Pol	Audi A6-TDi-Turbo Diesel	DBH569P	\$ 12.578
RT-569Vit	Audi A6-TDi-Turbo Diesel	DBH569V	\$ 19.625
RT-526/1Pol	Bedford 300 / Chevrolet 350	DBH526AP	\$ 1.286
RT-526Pol	Bedford 300 / Chevrolet 350	DBH526P	\$ 15.552
RT-571/1Pol	BMW 316i-318-518 - Motor 1.6/1.8	DBH571AP	\$ 1.163
RT-571/1Vit	BMW 316i-318-518 - Motor 1.6/1.8	DBH571AV	\$ 1.831
RT-571Pol	BMW 316i-318-518 - Motor 1.6/1.8	DBH571P	\$ 9.405
RT-571Vit	BMW 316i-318-518 - Motor 1.6/1.8	DBH571V	\$ 14.674
RT-572/1Pol	BMW 320i E30-520i E28-323i-Motor 2.0/2.3	DBH572AP	\$ 1.163
RT-572/1Vit	BMW 320i E30-520i E28-323i-Motor 2.0/2.3	DBH572AV	\$ 1.831
RT-572Pol	BMW 320i E30-520i E28-323i-Motor 2.0/2.3	DBH572P	\$ 14.066
RT-572Vit	BMW 320i E30-520i E28-323i-Motor 2.0/2.3	DBH572V	\$ 22.011
RT-574/1Pol	BMW 320i E36-520i E34-Motor 2.0 24 Val.	DBH574AP	\$ 1.163
RT-574/1Vit	BMW 320i E36-520i E34-Motor 2.0 24 Val.	DBH574AV	\$ 1.831
RT-574Pol	BMW 320i E36-520i E34-Motor 2.0 24 Val.	DBH574P	\$ 28.046
RT-574Vit	BMW 320i E36-520i E34-Motor 2.0 24 Val.	DBH574V	\$ 44.016
RT-573/1Pol	BMW318i E30-320i M3-E30-Motor1.8-2.3 16V	DBH573AP	\$ 1.163
RT-573/1Vit	BMW318i E30-320i M3-E30-Motor1.8-2.3 16V	DBH573AV	\$ 1.831
RT-573Pol	BMW318i E30-320i M3-E30-Motor1.8-2.3 16V	DBH573P	\$ 18.726
RT-573Vit	BMW318i E30-320i M3-E30-Motor1.8-2.3 16V	DBH573V	\$ 29.342
RT-549/1Pol	Carat-Senda-Saveiro(Motor 1.6/1.8)	DBH549AP	\$ 1.038
RT-549Pol	Carat-Senda-Saveiro(Motor 1.6/1.8)	DBH549P	\$ 8.415
RT-545/1Pol	Chevette	DBH545AP	\$ 1.163

RT-545Pol	Chevette	DBH545P	\$ 9.405
RT-504/1Pol	Chevrolet 400 / Pick Up C-10	DBH504AP	\$ 1.090
RT-504Pol	Chevrolet 400 / Pick Up C-10	DBH504P	\$ 13.172
RT-525/1Pol	Chevrolet Apache	DBH525AP	\$ 1.286
RT-525Pol	Chevrolet Apache	DBH525P	\$ 15.552
RT-515/1Pol	Citroen 2 CV (8 mm.)	DBH515AP	\$ 1.038
RT-515Pol	Citroen 2 CV (8 mm.)	DBH515P	\$ 4.248
RT-516/1Pol	Citroen 3 CV Ami 8 (8.5 mm.)	DBH516AP	\$ 1.038
RT-516Pol	Citroen 3 CV Ami 8 (8.5 mm.)	DBH516P	\$ 4.248
RT-575/1Pol	Citroen AX-BX-C15-AUXE-REFLEXIC-Motor1.4	DBH575AP	\$ 1.163
RT-575Pol	Citroen AX-BX-C15-AUXE-REFLEXIC-Motor1.4	DBH575P	\$ 9.405
RT-576/1Pol	Citroen AX-SAXO-Motor 1.4/1.5 Diesel	DBH576AP	\$ 1.163
RT-576Pol	Citroen AX-SAXO-Motor 1.4/1.5 Diesel	DBH576P	\$ 9.405
RT-577/1Pol	Citroen ZX-BERLINGO-C15-Motor1.6/1.7/1.8	DBH577AP	\$ 1.038
RT-577Pol	Citroen ZX-BERLINGO-C15-Motor1.6/1.7/1.8	DBH577P	\$ 8.415
RT-579/1Pol	Citroen ZX-XANTIA-AURA-Mot 1.7-1.9Diesel	DBH579AP	\$ 1.038
RT-579Pol	Citroen ZX-XANTIA-AURA-Mot 1.7-1.9Diesel	DBH579P	\$ 8.415
RT-578/1Pol	Citroen ZX-XANTIA-XSARA-Motor 1.6/1.9	DBH578AP	\$ 1.038
RT-578Pol	Citroen ZX-XANTIA-XSARA-Motor 1.6/1.9	DBH578P	\$ 8.415
RT-566/1Pol	Corsa-Motor 1.6-Monza '86 en adelante	DBH566AP	\$ 1.038
RT-566/1Vit	Corsa-Motor 1.6-Monza '86 en adelante	DBH566AV	\$ 1.635
RT-566Pol	Corsa-Motor 1.6-Monza '86 en adelante	DBH566P	\$ 8.415
RT-566Vit	Corsa-Motor 1.6-Monza '86 en adelante	DBH566V	\$ 13.087
RT-631Vit	Cummins Serie 6C/CT	DBH631V	\$ 78.670
RT-581Vit	DAEWOO 1.6/2.0 16V-Citroen C3/Fiat/Corsa	DBH581V	\$ 29.342
RT-580/1Pol	DAEWOO GTi-ESPERO-Motor 1.5/1.6/1.8/2.0	DBH580AP	\$ 1.163
RT-580/1Vit	DAEWOO GTi-ESPERO-Motor 1.5/1.6/1.8/2.0	DBH580AV	\$ 1.831
RT-580Pol	DAEWOO GTi-ESPERO-Motor 1.5/1.6/1.8/2.0	DBH580P	\$ 9.405
RT-580Vit	DAEWOO GTi-ESPERO-Motor 1.5/1.6/1.8/2.0	DBH580V	\$ 14.674
RT-581/1Pol	DAEWOO LEGANZA-NUBIRA-Motor 1.6/2.0 16 V	DBH581AP	\$ 1.163
RT-581/1Vit	DAEWOO LEGANZA-NUBIRA-Motor 1.6/2.0 16 V	DBH581AV	\$ 1.831
RT-581Pol	DAEWOO-1.6/2.0 16V-Citroen C3/Fiat/Corsa	DBH581P	\$ 18.726
RT-537/1Pol	Daihatsu - Charade	DBH537AP	\$ 1.211
RT-537Pol	Daihatsu - Charade	DBH537P	\$ 7.374
RT-538/1Pol	Daihatsu 2 cilindros	DBH538AP	\$ 1.211
RT-538Pol	Daihatsu 2 cilindros	DBH538P	\$ 4.946
RT-511/1Pol	Dodge 1500	DBH511AP	\$ 1.163
RT-511Pol	Dodge 1500	DBH511P	\$ 9.405
RT-524/1Pol	Dodge 1800	DBH524AP	\$ 1.137
RT-524Pol	Dodge 1800	DBH524P	\$ 9.204
RT-512/1Pol	Dodge GTX 8 Cilindros	DBH512AP	\$ 2.152
RT-512Pol	Dodge GTX 8 Cilindros	DBH512P	\$ 34.589
RT-508/1Pol	Fiat 125-128-147-Duna-Uno-Fiorino-Ducato	DBH508AP	\$ 1.038
RT-508/1Vit	Fiat 125-128-147-Duna-Uno-Fiorino-Ducato	DBH508AV	\$ 1.635
RT-508Pol	Fiat 125-128-147-Duna-Uno-Fiorino-Ducato	DBH508P	\$ 8.415
RT-508Vit	Fiat 125-128-147-Duna-Uno-Fiorino-Ducato	DBH508V	\$ 13.087
RT-520/1Pol	Fiat 1500 / Peugeot 403	DBH520AP	\$ 842
RT-520Pol	Fiat 1500 / Peugeot 403	DBH520P	\$ 6.828
RT-509Pol	Fiat 1600 con Capuchon	DBH509P	\$ 8.415
RT-509Vit	Fiat 1600 con Capuchon	DBH509V	\$ 13.087

RT-509/1Pol	Fiat 1600 con capuchón	DBH509AP	\$ 1.038
RT-509/1Vit	Fiat 1600 con capuchón	DBH509AV	\$ 1.635
RT-510Pol	Fiat 600 - 750 con Capuchon	DBH510P	\$ 6.828
RT-510/1Pol	Fiat 600 - 750 con Capuchón	DBH510AP	\$ 842
RT-544/1Pol	Fiat 600 S-133	DBH544AP	\$ 1.163
RT-544Pol	Fiat 600 S-133	DBH544P	\$ 9.405
RT-552/1Pol	Fiat Lada	DBH552AP	\$ 1.038
RT-552/1Vit	Fiat Lada	DBH552AV	\$ 1.635
RT-552Pol	Fiat Lada	DBH552P	\$ 8.415
RT-552Vit	Fiat Lada	DBH552V	\$ 13.087
RT-563/1Pol	Fiat Palio-Siena-Nafero y Diesel	DBH563AP	\$ 1.038
RT-563/1Vit	Fiat Palio-Siena-Nafero y Diesel	DBH563AV	\$ 1.635
RT-563Pol	Fiat Palio-Siena-Nafero y Diesel	DBH563P	\$ 8.415
RT-563Vit	Fiat Palio-Siena-Nafero y Diesel	DBH563V	\$ 13.087
RT-565/1Pol	Fiat Palio-Siena-Tempra - 16 Valvulas	DBH565AP	\$ 1.163
RT-565/1Vit	Fiat Palio-Siena-Tempra - 16 Valvulas	DBH565AV	\$ 1.831
RT-565Pol	Fiat Palio-Siena-Tempra - 16 Valvulas	DBH565P	\$ 18.726
RT-565Vit	Fiat Palio-Siena-Tempra - 16 Valvulas	DBH565V	\$ 29.342
RT-543/1Pol	Fiat Regatta 85-100 / Tempra 1.8-2.0	DBH543AP	\$ 1.038
RT-543/1Vit	Fiat Regatta 85-100 / Tempra 1.8-2.0	DBH543AV	\$ 1.635
RT-543Pol	Fiat Regatta 85-100 / Tempra 1.8-2.0	DBH543P	\$ 8.415
RT-543Vit	Fiat Regatta 85-100 / Tempra 1.8-2.0	DBH543V	\$ 13.087
RT-531/1Pol	Ford 4 Bancadas	DBH531AP	\$ 1.211
RT-531Pol	Ford 4 Bancadas	DBH531P	\$ 14.658
RT-505/1Pol	Ford 7 Bancadas	DBH505AP	\$ 1.286
RT-505Pol	Ford 7 Bancadas	DBH505P	\$ 15.552
RT-556/1Pol	Ford Escort - Motor 1.6	DBH556AP	\$ 1.163
RT-556/1Vit	Ford Escort - Motor 1.6	DBH556AV	\$ 1.635
RT-556Pol	Ford Escort - Motor 1.6	DBH556P	\$ 9.405
RT-556Vit	Ford Escort - Motor 1.6	DBH556V	\$ 13.087
RT-551/1Pol	Ford Escort 1.8 / Galaxy 2.0	DBH551AP	\$ 1.038
RT-551/1Vit	Ford Escort 1.8 / Galaxy 2.0	DBH551AV	\$ 1.635
RT-551Pol	Ford Escort 1.8 / Galaxy 2.0	DBH551P	\$ 8.415
RT-551Vit	Ford Escort 1.8 / Galaxy 2.0	DBH551V	\$ 13.087
RT-507/1Pol	Ford F 100	DBH507AP	\$ 1.260
RT-507Pol	Ford F 100	DBH507P	\$ 20.313
RT-609/1Pol	Ford F100-150-Motor Maxion-Diesel	DBH609AP	\$ 1.286
RT-609/1Vit	Ford F100-150-Motor Maxion-Diesel	DBH609AV	\$ 2.031
RT-609Pol	Ford F100-150-Motor Maxion-Diesel	DBH609P	\$ 10.394
RT-609Vit	Ford F100-150-Motor Maxion-Diesel	DBH609V	\$ 16.255
RT-611/1Pol	Ford RANGER ROVER-Motor 2.5 Turbo Diesel	DBH611AP	\$ 1.286
RT-611/1Vit	Ford RANGER ROVER-Motor 2.5 Turbo Diesel	DBH611AV	\$ 2.031
RT-610/1Vit	Ford RANGER-EXPLORER-Motor 4.0 cc.	DBH610AV	\$ 2.031
RT-610Vit	Ford RANGER-EXPLORER-Motor 4.0 cc.	DBH610V	\$ 16.255
RT-611Vit	Ford Ranger-GMC S-10-M.Maxion 2.5-2.8 TD	DBH611V	\$ 16.255
RT-546/1Pol	Ford Sierra 1.6 / Fiesta 1.8	DBH546AP	\$ 1.163
RT-546/1Vit	Ford Sierra 1.6 / Fiesta 1.8	DBH546AV	\$ 1.831
RT-546Pol	Ford Sierra 1.6 / Fiesta 1.8	DBH546P	\$ 9.405
RT-546Vit	Ford Sierra 1.6 / Fiesta 1.8	DBH546V	\$ 14.674
RT-535/1Pol	Ford Sierra 2.3	DBH535AP	\$ 1.260

RT-535Pol	Ford Sierra 2.3	DBH535P	\$ 10.198
RT-506/1Pol	Ford Taunus 2000 - 2300	DBH506AP	\$ 1.260
RT-506Pol	Ford Taunus 2000 - 2300	DBH506P	\$ 10.198
RT-528/1Pol	Gacel 1600 - 1800	DBH528AP	\$ 1.038
RT-528Pol	Gacel 1600 - 1800	DBH528P	\$ 8.415
RT-607/1Pol	GMC LUV-S10-STD-DLX-TD-Mot 2.5/2.8 T.D.	DBH607AP	\$ 1.286
RT-607/1Vit	GMC LUV-S10-STD-DLX-TD-Mot 2.5/2.8 T.D.	DBH607AV	\$ 2.031
RT-607Pol	GMC LUV-S10-STD-DLX-TD-Mot 2.5/2.8 T.D.	DBH607P	\$ 10.394
RT-607Vit	GMC LUV-S10-STD-DLX-TD-Mot 2.5/2.8 T.D.	DBH607V	\$ 16.255
RT-608/1Pol	GMC S10-D10-D20-D40-Motor Maxion S4/S4T	DBH608AP	\$ 1.286
RT-608/1Vit	GMC S10-D10-D20-D40-Motor Maxion S4/S4T	DBH608AV	\$ 2.031
RT-608Pol	GMC S10-D10-D20-D40-Motor Maxion S4/S4T	DBH608P	\$ 10.394
RT-608Vit	GMC S10-D10-D20-D40-Motor Maxion S4/S4T	DBH608V	\$ 16.255
RT-536/1Pol	Honda 4 cilindros	DBH536AP	\$ 1.211
RT-536/1Vit	Honda 4 cilindros	DBH536AV	\$ 2.423
RT-536Pol	Honda 4 cilindros	DBH536P	\$ 9.802
RT-553/1Pol	Indenor XD2-XD4	DBH553AP	\$ 842
RT-553Pol	Indenor XD2-XD4	DBH553P	\$ 6.828
RT-582/1Pol	ISUZU TROOPER-RODEO-Mot 2.5/2.8/3.1-T.D.	DBH582AP	\$ 1.286
RT-582/1Vit	ISUZU TROOPER-RODEO-Mot 2.5/2.8/3.1-T.D.	DBH582AV	\$ 2.031
RT-582Pol	ISUZU TROOPER-RODEO-Mot 2.5/2.8/3.1-T.D.	DBH582P	\$ 10.394
RT-582Vit	ISUZU TROOPER-RODEO-Mot 2.5/2.8/3.1-T.D.	DBH582V	\$ 16.255
RT-584/1Pol	JEEP CHEROKEE-Mot 2.1 TD-Mod.1983/85/95	DBH584AP	\$ 1.038
RT-584/1Vit	JEEP CHEROKEE-Mot 2.1 TD-Mod.1983/85/95	DBH584AV	\$ 1.635
RT-584Pol	JEEP CHEROKEE-Mot 2.1 TD-Mod.1983/85/95	DBH584P	\$ 8.415
RT-584Vit	JEEP CHEROKEE-Mot 2.1 TD-Mod.1983/85/95	DBH584V	\$ 13.087
RT-583Vit	JEEP WRANGLER-Motor 2.0-Mod. 1983-86-95	DBH583V	\$ 13.087
RT-583/1Pol	JEEP WRANGLER-Motor 2.0-Mod.1983-86-95	DBH583AP	\$ 1.038
RT-583/1Vit	JEEP WRANGLER-Motor 2.0-Mod.1983-86-95	DBH583AV	\$ 1.635
RT-583Pol	JEEP WRANGLER-Motor 2.0-Mod.1983-86-95	DBH583P	\$ 8.415
RT-542/1Pol	Mazda 4 cilindros	DBH542AP	\$ 1.038
RT-542Pol	Mazda 4 cilindros	DBH542P	\$ 8.415
RT-628Pol	Mercedes Benz	DBH628P	\$ 14.752
RT-628Vit	Mercedes Benz	DBH628V	\$ 29.227
RT-629Pol	Mercedes Benz	DBH629P	\$ 21.989
RT-629Vit	Mercedes Benz	DBH629V	\$ 43.699
RT-547/1Pol	Mercedes Benz 1521 - 1526	DBH547AP	\$ 1.809
RT-547Pol	Mercedes Benz 1521 - 1526	DBH547P	\$ 36.271
RT-559/1Pol	Mercedes Benz 180	DBH559AP	\$ 1.286
RT-559Pol	Mercedes Benz 180	DBH559P	\$ 10.394
RT-518/1Pol	Mercedes Benz 3500 - 1112 - 1114	DBH518AP	\$ 1.809
RT-518Pol	Mercedes Benz 3500 - 1112 - 1114	DBH518P	\$ 21.799
RT-539/1Pol	Mitsubishi L 100	DBH539AP	\$ 1.211
RT-539Pol	Mitsubishi L 100	DBH539P	\$ 9.802
RT-550/1Pol	Mitsubishi L200 - L300	DBH550AP	\$ 1.286
RT-550Pol	Mitsubishi L200 - L300	DBH550P	\$ 10.394
RT-550Vit	Mitsubishi L200 - L300	DBH550V	\$ 16.255
RT-517/1Pol	Motor Indenor X D 4	DBH517AP	\$ 842
RT-517Pol	Motor Indenor X D 4	DBH517P	\$ 6.828
RT-530/1Pol	Motor Indenor X D 6	DBH530AP	\$ 842

RT-530Pol	Motor Indenor X D 6	DBH530P	\$ 10.198
RT-555/1Pol	Motor VM	DBH555AP	\$ 1.163
RT-555Pol	Motor VM	DBH555P	\$ 9.405
RT-519/1Pol	Opel K 180	DBH519AP	\$ 1.286
RT-519Pol	Opel K 180	DBH519P	\$ 10.394
RT-529/1Pol	Passat	DBH529AP	\$ 1.038
RT-529Pol	Passat	DBH529P	\$ 8.415
RT-501/1Pol	Perkins 4-203	DBH501AP	\$ 1.195
RT-501Pol	Perkins 4-203	DBH501P	\$ 10.394
RT-502/1Pol	Perkins 6-305	DBH502AP	\$ 1.286
RT-502Pol	Perkins 6-305	DBH502P	\$ 15.552
RT-503/1Pol	Perkins 6-354	DBH503AP	\$ 1.286
RT-503Pol	Perkins 6-354	DBH503P	\$ 15.552
RT-614/1Vit	Peugeot 106-205-XR-XS-Mot 1.4/1.5-Diesel	DBH614AV	\$ 1.831
RT-614Vit	Peugeot 106-205-XR-XS-Mot 1.4/1.5-Diesel	DBH614V	\$ 14.674
RT-614/1Pol	Peugeot 106-205-XR-XS-Mot.1.4/1.5-Diesel	DBH614AP	\$ 1.163
RT-614Pol	Peugeot 106-205-XR-XS-Mot.1.4/1.5-Diesel	DBH614P	\$ 9.405
RT-557/1Pol	Peugeot 205-405 (Diesel y Naftero)	DBH557AP	\$ 1.038
RT-557Pol	Peugeot 205-405 (Diesel y Naftero)	DBH557P	\$ 8.415
RT-612/1Pol	Peugeot 205-OPEN-GTi-GR-GT-XR-XS-Mot 1.6	DBH612AP	\$ 1.038
RT-612Pol	Peugeot 205-OPEN-GTi-GR-GT-XR-XS-Mot 1.6	DBH612P	\$ 8.415
RT-615/1Pol	Peugeot 206-306-406-Mot 1.8/2.0-16 Val.	DBH615AP	\$ 1.163
RT-615/1Vit	Peugeot 206-306-406-Mot 1.8/2.0-16 Val.	DBH615AV	\$ 1.831
RT-615Pol	Peugeot 206-306-406-Mot 1.8/2.0-16 Val.	DBH615P	\$ 18.726
RT-615Vit	Peugeot 206-306-406-Mot 1.8/2.0-16 Val.	DBH615V	\$ 29.342
RT-613/1Pol	Peugeot 306-405-406-805-Mot 1.7-1.9 T.D.	DBH613AP	\$ 1.038
RT-613Pol	Peugeot 306-405-406-805-Mot 1.7-1.9 T.D.	DBH613P	\$ 8.415
RT-616/1Pol	Peugeot 405-306-406-806-BOXER-Motor 2.0	DBH616AP	\$ 1.163
RT-616/1Vit	Peugeot 405-306-406-806-BOXER-Motor 2.0	DBH616AV	\$ 1.831
RT-616Pol	Peugeot 405-306-406-806-BOXER-Motor 2.0	DBH616P	\$ 18.726
RT-616Vit	Peugeot 405-306-406-806-BOXER-Motor 2.0	DBH616V	\$ 29.342
RT-617/1Pol	Peugeot 406-605-805-Mot 2.1-Turbo Diesel	DBH617AP	\$ 1.038
RT-617/1Vit	Peugeot 406-605-805-Mot 2.1-Turbo Diesel	DBH617AV	\$ 1.635
RT-617Pol	Peugeot 406-605-805-Mot 2.1-Turbo Diesel	DBH617P	\$ 12.578
RT-617Vit	Peugeot 406-605-805-Mot 2.1-Turbo Diesel	DBH617V	\$ 19.625
RT-533/1Pol	Peugeot 505	DBH533AP	\$ 1.038
RT-533Pol	Peugeot 505	DBH533P	\$ 8.415
RT-618/1Pol	Peugeot 605 - Motor 3.0 - 24 Valvulas	DBH618AP	\$ 1.163
RT-618/1Vit	Peugeot 605 - Motor 3.0 - 24 Valvulas	DBH618AV	\$ 1.831
RT-618Pol	Peugeot 605 - Motor 3.0 - 24 Valvulas	DBH618P	\$ 28.046
RT-618Vit	Peugeot 605 - Motor 3.0 - 24 Valvulas	DBH618V	\$ 44.016
RT-513/1Pol	Peugeot 8 mm. desde 1970	DBH513AP	\$ 1.038
RT-513Pol	Peugeot 8 mm. desde modelo 1970	DBH513P	\$ 8.415
RT-514/1Pol	Peugeot 8,5 mm. hasta modelo 1969	DBH514AP	\$ 1.211
RT-514Pol	Peugeot 8,5 mm. hasta modelo 1969	DBH514P	\$ 9.802
RT-521Pol	Rastrojero Capuchon 9 mm.	DBH521P	\$ 6.828
RT-521/1Pol	Rastrojero capuchón 9 mm.	DBH521AP	\$ 842
RT-620/1Pol	Renault - Motor 1.800 - 16 Valvulas	DBH620AP	\$ 1.163
RT-620/1Vit	Renault - Motor 1.800 - 16 Valvulas	DBH620AV	\$ 1.831
RT-620Pol	Renault - Motor 1.800 - 16 Valvulas	DBH620P	\$ 18.726

RT-620Vit	Renault - Motor 1.800 - 16 Valvulas	DBH620V	\$ 29.342
RT-560/1Pol	Renault - Motor 1600 cc.	DBH560AP	\$ 1.163
RT-560/1Vit	Renault - Motor 1600 cc.	DBH560AV	\$ 1.831
RT-560Pol	Renault - Motor 1600 cc.	DBH560P	\$ 9.405
RT-560Vit	Renault - Motor 1600 cc.	DBH560V	\$ 14.674
RT-561/1Pol	Renault - Motor 1700 y 1900 cc.	DBH561AP	\$ 1.038
RT-561/1Vit	Renault - Motor 1700 y 1900 cc.	DBH561AV	\$ 1.635
RT-561Pol	Renault - Motor 1700 y 1900 cc.	DBH561P	\$ 8.415
RT-561Vit	Renault - Motor 1700 y 1900 cc.	DBH561V	\$ 13.087
RT-622/1Pol	Renault - Motor ENERGY 1.3/1.4/1.6	DBH622AP	\$ 1.163
RT-622/1Vit	Renault - Motor ENERGY 1.3/1.4/1.6	DBH622AV	\$ 1.831
RT-622Pol	Renault - Motor ENERGY 1.3/1.4/1.6	DBH622P	\$ 9.405
RT-622Vit	Renault - Motor ENERGY 1.3/1.4/1.6	DBH622V	\$ 14.674
RT-594Pol	Renault Clio 2 - Megane 2 - Logan 1.5Dci	DBH594P	\$ 9.405
RT-594Vit	Renault Clio2-Megane2-Logan Motor 1.5Dci	DBH594V	\$ 14.674
RT-594/1Pol	Renault Megane 2 - Clio 2 - 1.5 dci	DBH594AP	\$ 1.163
RT-594/1Vit	Renault Megane2 - clio2 - Motor 1.5 dci	DBH594AV	\$ 1.831
RT-534/1Pol	Renault R18-R21-Trafic-Motor 1.6/1.7/2.0	DBH534AP	\$ 1.038
RT-534/1Vit	Renault R18-R21-Trafic-Motor 1.6/1.7/2.0	DBH534AV	\$ 1.635
RT-534Pol	Renault R18-R21-Trafic-Motor 1.6/1.7/2.0	DBH534P	\$ 8.415
RT-534Vit	Renault R18-R21-Trafic-Motor 1.6/1.7/2.0	DBH534V	\$ 13.087
RT-523/1Pol	Renault R6-R12-Dacia-Motor 1.3 y 1.4	DBH523AP	\$ 1.038
RT-523Pol	Renault R6-R12-Dacia-Motor 1.3 y 1.4	DBH523P	\$ 8.415
RT-527/1Pol	Renault R9-R18-R19-Clio-Motor 1.4 y 1.6	DBH527AP	\$ 1.038
RT-527Pol	Renault R9-R18-R19-Clio-Motor 1.4 y 1.6	DBH527P	\$ 8.415
RT-619/1Pol	Renault-Motor 1.900 Diesel-Posterior '97	DBH619AP	\$ 1.163
RT-619/1Vit	Renault-Motor 1.900 Diesel-Posterior '97	DBH619AV	\$ 1.831
RT-619Pol	Renault-Motor 1.900 Diesel-Posterior '97	DBH619P	\$ 9.405
RT-619Vit	Renault-Motor 1.900 Diesel-Posterior '97	DBH619V	\$ 14.674
RT-621/1Pol	Renault-Motor 2.200 Diesel-Posterior '97	DBH621AP	\$ 1.163
RT-621/1Vit	Renault-Motor 2.200 Diesel-Posterior '97	DBH621AV	\$ 1.831
RT-621Pol	Renault-Motor 2.200 Diesel-Posterior '97	DBH621P	\$ 14.066
RT-621Vit	Renault-Motor 2.200 Diesel-Posterior '97	DBH621V	\$ 22.011
RT-623/1Pol	Renault-Motor 2.4-20 Valvulas-Post. '98	DBH623AP	\$ 1.163
RT-623/1Vit	Renault-Motor 2.4-20 Valvulas-Post. '98	DBH623AV	\$ 1.831
RT-623Pol	Renault-Motor 2.4-20 Valvulas-Post. '98	DBH623P	\$ 23.386
RT-623Vit	Renault-Motor 2.4-20 Valvulas-Post. '98	DBH623V	\$ 36.679
RT-554/2Pol	Reten Deutz 913	DBH554P	\$ 1.110
RT-586/1Pol	Rover 114 D-115 D-Mot 1.4 DT -Mod. 92/94	DBH586AP	\$ 1.163
RT-586/1Vit	Rover 114 D-115 D-Mot 1.4 DT -Mod. 92/94	DBH586AV	\$ 1.831
RT-586Pol	Rover 114 D-115 D-Mot 1.4 DT -Mod. 92/94	DBH586P	\$ 9.405
RT-586Vit	Rover 114 D-115 D-Mot 1.4 DT -Mod. 92/94	DBH586V	\$ 14.674
RT-585/1Pol	Rover 218 SLD-418 D - Motor 1.7/1.9 cc.	DBH585AP	\$ 1.038
RT-585/1Vit	Rover 218 SLD-418 D - Motor 1.7/1.9 cc.	DBH585AV	\$ 1.635
RT-585Pol	Rover 218 SLD-418 D - Motor 1.7/1.9 cc.	DBH585P	\$ 8.415
RT-585Vit	Rover 218 SLD-418 D - Motor 1.7/1.9 cc.	DBH585V	\$ 13.087
RT-587Vit	Rover RANGE - Motor 2.5 - Turbo Diesel	DBH587V	\$ 22.011
RT-587/1Pol	Rover RANGE - Motor 2.5 Turbo Diesel	DBH587AP	\$ 1.163
RT-587/1Vit	Rover RANGE - Motor 2.5 Turbo Diesel	DBH587AV	\$ 1.831
RT-587Pol	Rover RANGE - Motor 2.5 Turbo Diesel	DBH587P	\$ 14.066

RT-588/1Pol	Saab 9-3 - Motor 2.0 - 16 Valvulas	DBH588AP	\$ 1.163
RT-588/1Vit	Saab 9-3 - Motor 2.0 - 16 Valvulas	DBH588AV	\$ 1.831
RT-588Pol	Saab 9-3 - Motor 2.0 - 16 Valvulas	DBH588P	\$ 18.815
RT-588Vit	Saab 9-3 - Motor 2.0 - 16 Valvulas	DBH588V	\$ 29.342
RT-591/1Pol	Seat 1.9 TDi - Diesel - Post. '95	DBH591AP	\$ 1.163
RT-591/1Vit	Seat 1.9 TDi - Diesel - Post. '95	DBH591AV	\$ 1.831
RT-591Pol	Seat 1.9 TDi - Diesel - Post. '95	DBH591P	\$ 9.405
RT-591Vit	Seat 1.9 TDi - Diesel - Post. '95	DBH591V	\$ 14.674
RT-589Vit	Seat CORDOBA-IBIZA-TOLEDO-Mot. 1.0/1.6	DBH589V	\$ 13.087
RT-589/1Pol	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.0/1.6	DBH589AP	\$ 1.038
RT-589/1Vit	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.0/1.6	DBH589AV	\$ 1.635
RT-589Pol	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.0/1.6	DBH589P	\$ 8.415
RT-592/1Pol	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.6/1.8/20	DBH592AP	\$ 1.163
RT-592/1Vit	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.6/1.8/20	DBH592AV	\$ 1.831
RT-592Pol	Seat CORDOBA-IBIZA-TOLEDO-Mot.1.6/1.8/20	DBH592P	\$ 9.405
RT-592Vit	Seat CORDOBA-IBIZA-TOLEDO-Mot1.6/1.8/2.0	DBH592V	\$ 14.674
RT-590/1Pol	Seat CORDOBA-TOLEDO-Mot 1.8/2.0 GTi-16 V	DBH590AP	\$ 1.163
RT-590/1Vit	Seat CORDOBA-TOLEDO-Mot 1.8/2.0 GTi-16 V	DBH590AV	\$ 1.831
RT-590Pol	Seat CORDOBA-TOLEDO-Mot 1.8/2.0 GTi-16 V	DBH590P	\$ 18.815
RT-590Vit	Seat CORDOBA-TOLEDO-Mot 1.8/2.0 GTi-16 V	DBH590V	\$ 29.342
RT-593/1Pol	Seat IBIZA-CORDOBA-TOLEDO-Mot 1.9 SDi	DBH593AP	\$ 1.038
RT-593/1Vit	Seat IBIZA-CORDOBA-TOLEDO-Mot 1.9 SDi	DBH593AV	\$ 1.635
RT-593Pol	Seat IBIZA-CORDOBA-TOLEDO-Mot 1.9 SDi	DBH593P	\$ 8.415
RT-593Vit	Seat IBIZA-CORDOBA-TOLEDO-Mot 1.9 SDi	DBH593V	\$ 13.087
RT-522/1Pol	Siam Di Tella 1500	DBH522AP	\$ 1.237
RT-522Pol	Siam Di Tella 1500	DBH522P	\$ 9.998
RT-595/1Pol	Skoda FAVORIT-FORMAN-Mot 1.1/1.3-Post'95	DBH595AP	\$ 1.038
RT-595/1Vit	Skoda FAVORIT-FORMAN-Mot 1.1/1.3-Post'95	DBH595AV	\$ 1.635
RT-595Pol	Skoda FAVORIT-FORMAN-Mot 1.1/1.3-Post'95	DBH595P	\$ 8.415
RT-595Vit	Skoda FAVORIT-FORMAN-Mot 1.1/1.3-Post'95	DBH595V	\$ 13.087
RT-596/1Pol	Skoda FAVORIT-RAPID-Motor 1.6/1.9	DBH596AP	\$ 1.038
RT-596/1Vit	Skoda FAVORIT-RAPID-Motor 1.6/1.9	DBH596AV	\$ 1.635
RT-596Pol	Skoda FAVORIT-RAPID-Motor 1.6/1.9	DBH596P	\$ 8.415
RT-596Vit	Skoda FAVORIT-RAPID-Motor 1.6/1.9	DBH596V	\$ 13.087
RT-598Vit	Skoda FELICIA-OCTAVIA-Motor 1.9 SDi/TDi	DBH598V	\$ 14.674
RT-598/1Pol	Skoda FELICIA-OCTAVIA-Motor 1.9 SDi-TDi	DBH598AP	\$ 1.163
RT-598/1Vit	Skoda FELICIA-OCTAVIA-Motor 1.9 SDi-TDi	DBH598AV	\$ 1.831
RT-598Pol	Skoda FELICIA-OCTAVIA-Motor 1.9 SDi-TDi	DBH598P	\$ 9.405
RT-597/1Pol	Skoda OCTAVIA-FELICIA-Mot 1.6 AEE-Pos'95	DBH597AP	\$ 1.163
RT-597/1Vit	Skoda OCTAVIA-FELICIA-Mot 1.6 AEE-Pos'95	DBH597AV	\$ 1.831
RT-597Pol	Skoda OCTAVIA-FELICIA-Mot 1.6 AEE-Pos'95	DBH597P	\$ 9.405
RT-597Vit	Skoda OCTAVIA-FELICIA-Mot 1.6 AEE-Pos'95	DBH597V	\$ 14.674
RT-599/1Pol	Ssang Yong Musso - Motor 3.2-24 Valvulas	DBH599AP	\$ 1.163
RT-599/1Vit	Ssang Yong Musso - Motor 3.2-24 Valvulas	DBH599AV	\$ 1.831
RT-599Pol	Ssang Yong Musso - Motor 3.2-24 Valvulas	DBH599P	\$ 28.046
RT-599Vit	Ssang Yong Musso - Motor 3.2-24 Valvulas	DBH599V	\$ 44.016
RT-600/1Pol	Suzuki VITARA 4 x 4 - Motor 1.9 D/TD	DBH600AP	\$ 1.038
RT-600/1Vit	Suzuki VITARA 4 x 4 - Motor 1.9 D/TD	DBH600AV	\$ 1.635
RT-600Pol	Suzuki VITARA 4 x 4 - Motor 1.9 D/TD	DBH600P	\$ 8.415
RT-600Vit	Suzuki VITARA 4 x 4 - Motor 1.9 D/TD	DBH600V	\$ 13.087

RT-500/1Pol	Torino 4 B y 7 B	DBH500AP	\$ 1.286
RT-500Pol	Torino 4 B y 7 B	DBH500P	\$ 15.552
RT-541/1Pol	Toyota Camioneta 2.000	DBH541AP	\$ 1.286
RT-541Pol	Toyota Camioneta 2.000	DBH541P	\$ 10.394
RT-548/1Pol	Toyota Celica - Motor 2.0	DBH548AP	\$ 1.286
RT-548Pol	Toyota Celica - Motor 2.0	DBH548P	\$ 10.394
RT-540Pol	Toyota Celica 1.600 cc.	DBH540P	\$ 10.394
RT-540/1Pol	Toyota Célica 1.600 cc.	DBH540AP	\$ 1.286
RT-532/1Pol	Valiant I - II - III - IV	DBH532AP	\$ 2.152
RT-532Pol	Valiant I-II-III-IV	DBH532P	\$ 14.579
RT-564/1Pol	Volkswagen Gol y Polo - Motor 1.9	DBH564AP	\$ 1.163
RT-564/1Vit	Volkswagen Gol y Polo - Motor 1.9	DBH564AV	\$ 1.831
RT-564Pol	Volkswagen Gol y Polo - Motor 1.9	DBH564P	\$ 9.405
RT-564Vit	Volkswagen Gol y Polo - Motor 1.9	DBH564V	\$ 14.674
RT-624/1Pol	Volkswagen GOL-SAVEIRO-Mot. 1.5/1.6 CHT	DBH624AP	\$ 1.038
RT-624/1Vit	Volkswagen GOL-SAVEIRO-Mot. 1.5/1.6 CHT	DBH624AV	\$ 1.635
RT-624Pol	Volkswagen GOL-SAVEIRO-Mot. 1.5/1.6 CHT	DBH624P	\$ 8.415
RT-624Vit	Volkswagen GOL-SAVEIRO-Mot. 1.5/1.6 CHT	DBH624V	\$ 13.087
RT-625/1Pol	Volkswagen PASSAT-GOLF-Motor 1.8- 20 Val	DBH625AP	\$ 1.163
RT-625Pol	Volkswagen PASSAT-GOLF-Motor 1.8- 20 Val	DBH625P	\$ 23.386
RT-627/1Pol	Volkswagen PASSAT-VARIANT-GOLF-Motor 2.8	DBH627AP	\$ 1.163
RT-627/1Vit	Volkswagen PASSAT-VARIANT-GOLF-Motor 2.8	DBH627AV	\$ 1.831
RT-627Pol	Volkswagen PASSAT-VARIANT-GOLF-Motor 2.8	DBH627P	\$ 14.066
RT-627Vit	Volkswagen PASSAT-VARIANT-GOLF-Motor 2.8	DBH627V	\$ 22.011
RT-626/1Pol	Volkswagen TRANSP. T4-MULTIVAN-Mot 2.4 D	DBH626AP	\$ 1.038
RT-626/1Vit	Volkswagen TRANSP. T4-MULTIVAN-Mot 2.4 D	DBH626AV	\$ 1.635
RT-626Pol	Volkswagen TRANSP. T4-MULTIVAN-Mot 2.4 D	DBH626P	\$ 10.495
RT-626Vit	Volkswagen TRANSP. T4-MULTIVAN-Mot 2.4 D	DBH626V	\$ 16.356
RT-562/1Pol	Volkswagen-Gol-Polo-Motor 1600-1800 cc.	DBH562AP	\$ 1.038
RT-562Pol	Volkswagen-Gol-Polo-Motor 1600-1800 cc.	DBH562P	\$ 8.415
RT-606/1Pol	Volvo 240-244-245-740-760-940-Mot 2.4 D	DBH606AP	\$ 1.038
RT-606/1Vit	Volvo 240-244-245-740-760-940-Mot 2.4 D	DBH606AV	\$ 1.635
RT-606Pol	Volvo 240-244-245-740-760-940-Mot 2.4 D	DBH606P	\$ 12.578
RT-606Vit	Volvo 240-244-245-740-760-940-Mot 2.4 D	DBH606V	\$ 19.625
RT-605/1Pol	Volvo 850-S70-V70-370-Mot 2.5 TDi-10 Val	DBH605AP	\$ 1.163
RT-605/1Vit	Volvo 850-S70-V70-370-Mot 2.5 TDi-10 Val	DBH605AV	\$ 1.831
RT-605Pol	Volvo 850-S70-V70-370-Mot 2.5 TDi-10 Val	DBH605P	\$ 11.732
RT-605Vit	Volvo 850-S70-V70-370-Mot 2.5 TDi-20 Val	DBH605V	\$ 18.340
RT-604/1Pol	Volvo 960-S90-V90-S70-S80-Mot 2.9-24 Val	DBH604AP	\$ 1.163
RT-604/1Vit	Volvo 960-S90-V90-S70-S80-Mot 2.9-24 Val	DBH604AV	\$ 1.831
RT-604Pol	Volvo 960-S90-V90-S70-S80-Mot 2.9-24 Val	DBH604P	\$ 28.046
RT-604Vit	Volvo 960-S90-V90-S70-S80-Mot 2.9-24 Val	DBH604V	\$ 44.016
RT-602Vit	Volvo S40-V40 Mot 1.9/2.0 16Val.Post. '96	DBH602V	\$ 29.342
RT-601/1Pol	Volvo S40-V40-440-460-Motor 1.9 - TD	DBH601AP	\$ 1.038
RT-601/1Vit	Volvo S40-V40-440-460-Motor 1.9 - TD	DBH601AV	\$ 1.635
RT-601Pol	Volvo S40-V40-440-460-Motor 1.9 - TD	DBH601P	\$ 8.415
RT-601Vit	Volvo S40-V40-440-460-Motor 1.9 - TD	DBH601V	\$ 13.087
RT-602/1Pol	Volvo S40-V40-Mot 1.9/2.0 16Val.Post. '96	DBH602AP	\$ 1.163
RT-602/1Vit	Volvo S40-V40-Mot 1.9/2.0 16Val.Post. '96	DBH602AV	\$ 1.831
RT-602Pol	Volvo S40-V40-Mot 1.9/2.0 16Val.Post. '96	DBH602P	\$ 18.726

RT-603/1Pol	Volvo V40-850-S70-V70-C70-Mot2.0/2.4 20V	DBH603AP	\$ 1.163
RT-603/1Vit	Volvo V40-850-S70-V70-C70-Mot2.0/2.4 20V	DBH603AV	\$ 1.831
RT-603Pol	Volvo V40-850-S70-V70-C70-Mot2.0/2.4 20V	DBH603P	\$ 23.386
RT-603Vit	Volvo V40-850-S70-V70-C70-Mot2.0/2.5 20V	DBH603V	\$ 36.679

